



NO COMPROMISE

APPENDIX B

Locking Piece (Steuerstücke) Guide:

Part #	Angle	Marking	Weapon	Notes
200439	45°	None	G3 A3/A4 G3 Export G3 SG/1 HK91 A2/A3	
201599	100°	None	MP5 A2/A3/A4/A5 MP5 K/KN MP5 N MP5 PT HK94 A2/A3	Replaces 224786
225629	100°	None	MP5 Maritime	(Maritime Coating)
202096	40°	1	HK11	(Old)
200001	50°	2	HK21 Portugal	(Old)
203384	58°	3	HK33K HK53	(M885 w/ 1 in 7" ROT)
202537	45°	4	HK21	(Old)
205929	120°	5	MPSD	(Old)
203479	58°	6	HK13	(Old)
200306	55°	7	HK33 E HK33 SG/1 HK93 A2/A3	
203386	55°	8	HK33	Malaysia
222102	40°	9	HK11 A2/A3	(Old)
203497	55°	10	HK13	(Old)
221189	45°	12	HK21 A1	(Old)
206685	70°	13	HK53	(Old)
222163	58°	14	HK13 A3	(Old)
224687	65°	15	HK53	(M193)
224786	110°	16	MP5 K	(Old)

HECKLER & KOCH

19980 Highland Vista Drive, Suite #190, Ashburn, Virginia 20147 USA
Tel: (703) 450-1900 Fax: (703) 450-8160 www.heckler-koch.com

GERMANY . USA . UNITED KINGDOM . FRANCE



NO COMPROMISE

Part #	Angle	Marking	Weapon	Notes
228142	36°	17	HK11 E HK21 E G8 & G8A1	
224336	36°	17A	G41 A2	
224888	50°	18	G3 K	
225023	40°	19	PSG1	(Old)
222987	70°	20T	HK23E HK13 E	Titanium Coated
225312	43°	21	G41	
225313	43°	21A	G41	
225310	45°	22	G41 K	
225311	45°	22A	G41 K	
225726	40°	23T	MSG90 MSG90A1 PSG1	Old/Titanium Coated Replaced by 214722
205189	90°	24 LO	MP5/10 MP5/40	New; Replaces 205355
205282	60°	25 HI	MP5/10	
205355	80°	26	MP5/40	(Old)
214291	90°	27	MP5 K	
214292	80°	28	MP5 K PDW	(New)
214293	70°	29	MP5 K MP5 KN	
214722	45°	30T	MSG90 MSG90A1 PSG1	New/Titanium Coated Replaces 225726 & 225023
214292	80°	80°	MP5 K PDW	Old
205316	115°	MP5 Action MP5 SD	MP5 SD	Replaces 205929

Updated MAY 07

HECKLER & KOCH
19980 Highland Vista Drive, Suite #190, Ashburn, Virginia 20147 USA
Tel: (703) 450-1900 Fax: (703) 450-8160 www.heckler-koch.com

GERMANY . USA . UNITED KINGDOM . FRANCE